

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

RECEIVED  
BLM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

Lease Designation and Serial No.

12335

6. If Indian, Allottee or Tribe Name

7. If Indian, CA, Agreement Designation

SUBMIT IN TRIPLICATE

019 FARMINGTON, N.M.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Citation Oil & Gas Corp.

713-469-9664

3. Address and Telephone No.

8223 Willow Place South Ste 250 Houston, Texas 77070

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1646'FNL & 2667'FEL Sec. 12-17N-9W

8. Well Name and No.

South Hospah Unit # 66

9. API Well No.

10. Field and Pool, or Exploratory Area

S. Hospah L.P. S.

11. County or Parish, State

McKinley County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other Plug and abandon

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Citation Oil & Gas Corp. request permission to plug and abandon this well by using the following procedure:

1. TIH w/open-end 2 7/8" tbg to retainer at 1619 ft. Spot 61 sx Class B cmt w/2% Cacl2. Pull up to +/- 1200 ft, reverse circulate until clean. WOC 2 hrs.
2. Tag TOC. Spot 9 ppg mud from TOC to +/- 580 ft. Pull tbg to 580 ft. Pump 170 sx Class B neat (volume will fill csg and tbg to surface). LD tbg. Top off csg when 1 jt remains in hole. LD jt.
3. Cut off casing and weld on plate with 4" x 4' marker post. Clean location.

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed

Sharon E Ward

Title Production Regulatory Supv

Date 9-29-92

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date 9-29-92

AREA MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

RM000