



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

May 24, 1983

Mr. Gerald J. Prom
13812 N.E. Clark Road
Vancouver WA 98665

Re: Crownpoint #1, F-18-18N-13W


Dear Mr. Prom;

After reviewing the reports from L & C Pump & Pipe, Inc., it is our opinion that the only feasible way to plug the referenced well is to move a small rig over the hole and run tubing. The last time I was on this location it was flooded from a nearby water well and may have to be drained before rigging up.

In order to avoid having a demand placed on Western Surety Company to plug the well, I urge you to initiate immediate plugging action.

Enclosed is a copy of the Division approved plugging program.

Yours truly,


Charles Gholson

cc: Perry Pearce
Dick Stamets
Reading File
Well File ✓

gh/al