Form 9-331 (May 1963)

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

UNITED STATES SUBMIT IN TRIPLICATES Of the instructions on reverse side) **UNITED STATES** GEOLOGICAL SURVEY

SHOOTING OR ACIDIZING

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

NM-13053-A

SUNDRY NOTICES AND REPORTS ON WELLS

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

ABANDONMENT*

	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)								
	OIL X GAS OTHER	7. UNIT AGREEMENT NA	M E						
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME							
	WTR OIL COMPANY	Federal							
3.	ADDRESS OF OPERATOR	9. WELL NO.							
	c/o Mark E. Weidler, 415 W. Main, Farmington, N.M. 87401	1 81-79 -1							
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Wildcat							
	350'FEL, 330'FSL	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA SEC. 9-T18N-R12W							
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	N.M.P.M.	13. STATE						
	6434	McKinley	N.M.						
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data								
	NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:							
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING W							
	FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALIERING CA	151110						

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2-02-81 This well was plugged and abandoned in the following manner:

> Surface to 140', 35 sacks 270' to 570', 70 sacks 1110' to 1400', 80 sacks 2050' to 2220' 50 sacks Set dry hole marker at surface.

ABANDON*

CHANGE PLANS

NOV 2 6 11 21

FOR:	Wall Cam College							
8. I hereb	y corner man the day going is true and correct		President,	Walsh	Engr.	&		
SIGNE	EWELL N. WALSH	TITLE	Production	Corp.		ДΑТ	2/02/81	
	Ewell N. Walsh, P.E.							
(This s	space for Federal or State office use)					API	FACNIDE	D
APPRO	ED BY	TITLE				_ASAF	MENDE	
CONDI	CONDITIONS OF APPROVAL, IF ANY:						CT 23 1984	
						U	11 20 100	

Approved as to plugging of the well bore.

Liability under bond is retained until surface restoration is aammlatad

Instructions on Reverse Side

M. MILLENBACH AREA MANAGER