

EXHIBIT "A"

BIRD FEDERAL 12-11

SUBSEQUENT REPORT OF ABANDONMENT

Reason for Abandonment: Uneconomic to produce.

Plugged to Abandon as follows: (per written permission by Errol Becher 08-Mar-84)

08 & 09-Mar-84: RIH open ended with 2-3/8" tubing to 2023.6'.
Loaded hole with 9.2 ppg mud.

	<u>Interval</u>	<u>Formation</u>	<u>Volume</u>	<u>Material</u>
Plug #1	2023.6-1938'	Pt. Lookout	8.4 ft ³	Class A 3% CaCl
Plug #2	1162 -1062'	Cliff Hse.-Menefee	8.9 ft ³	Class A 3% CaCl
Plug #3	638 - 538'	Chacra-Cliff House	8.9 ft ³	Class A 3% CaCl
Plug #4	142 -surface	Pictured Cliffs	12.7 ft ³	Class A 3% CaCl

Plug #1 tagged OK @ 1938' after WOC. All slurries displaced with 9.2 ppg mud.
Operations witnessed by Larry Picksley.

4½" O.D. dry hole marker screwed into top of casing.

No formations left unsealed.

All 4½" casing left intact.

Wellsite to be graded and reseeded in July 1984.

APR 11 1984
CL CON. DIV.
DNT. 9