Distribution:

Orig+4 (BLM); 1-Crystal; 1-Accounting;

1-Well File

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

JNDRY NOTICES	AND REF	PORTS	ON	WELLS
---------------	---------	-------	----	-------

NO-G-9208-1236 6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Well X Gas Well 8. Well Name and No. Chaco Wash No. 1 2. Name of Operator Q API Well No Merrion Oil & Gas Corporation 30-031-20975 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area (505) 327-9801 P. O. Box 840, Farmington, New Mexico 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) **Undesignated Gallup** 11. County or Parish, State McKinley, 1820' FSL & 1850' FEL **New Mexico** Section 13, T20N, R6W 12

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	X Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing	Conversion to Injection	
	Other	Dispose Water	
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent give subsurface locations and measured and true vertical depths
- and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, markers and zones pertinent to this work.)4
- MIRU A-Plus Well Service Rig No. 4. Lay out relief lines to pit and bleed well. Pump 20 bbls to kill well. Rig up rig and cementing equipment. ND wellhead. PU on tubing and was free. NU BOP. TOH and tally 119 joints of 2-3/8" tbg @ 3007'. TIH with perf sub and 122 jts of 2-3/8" tbg to 3912' (Plug #1) with tubing at 3912' and pump 30 bbls, mix 150 sxs Class B neat cement (15.5#) and displace from 3912' up to 3111'. Pull and lay down tubing up to 3105'. Stand back 15 stands and WOC.
- Open well up had 0 psi. TIH and tag Plug #1 at 3138'. Pull and lay down tubing up to 1455' with 53 joints 6/14/94 (Plug #2) with tubing on 1455', load hole with 110 bbls and casing to 500 psi - held OK. Mix 60 sxs of Class B neat cement (15.4#) and displace from 1455' up to 1138'. Pull and lay down tubing and perf sub. RU wireline and RIH and perforated 2 holes at 590'. RD wireline. Establish circulation down casing and out bradenhead with 30 bbls. (Plug #3) mixed 178 sxs of Class B neat cement with 16.5# and got 1 good cement out bradenhead. Shut well in and WOC. Open up well. ND BOP. Cut off wellhead and installed dry hole marker with 20 sxs ceme Will rehabilitate location at a later date.

that the foregoing is true and correct Operations Manager 6/15/94 110 Signed (This space for Federal Con See Principle) Approved by Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States Int. Talse, 14 inc. of the United States Int. of or representations as to any matter within its jurisdiction