

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-039-05077</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <b>N/A</b>
7. Lease Name or Unit Agreement Name <b>Florence Millenbaugh</b>
8. Well No. <b>#2</b>
9. Pool name or Wildcat <b>Blanco Pictured Cliffs</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>EOG (New Mexico) Inc.</b>	3. Address of Operator <b>621 17th St., Suite 1800, Denver, CO. 80293</b>
4. Well Location Unit Letter <b>B</b> : <b>990</b> Feet From The <b>FNL</b> Line and <b>1650</b> Feet From The <b>FEL</b> Line <b>18</b> Section <b>23N</b> Township <b>1W</b> Range <b>NMPM</b> <b>Rio Arriba</b> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <b>MIT Test</b> <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) EPNG Locate Gas Lines
- 2) Set 4 anchors
- 3) MIRU PU
- 4) POH 1-1/2" tbg. LD on float
- 5) Notify NMOCC to witness
- 6) RIH 2-3/8" Workstring & 4-1/2" Mod "R" packer
- 7) Set packer
- 8) Press test 4-1/2" x 2-3/8" annulus to NMOCC specs
- 9) POH 2-3/8" tbg & packer. LD on float
- 10) NU valve on casing
- 11) SI well. If needs repair, will repair later.

RECEIVED  
MAY - 9 1994  
OIL CON. DIV.  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Conni Smith TITLE Sr. Engineering Tech DATE 5/6/94  
TYPE OR PRINT NAME Conni Smith TELEPHONE NO. \_\_\_\_\_

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAY 13 1994  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_