

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Shut-in

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface Unit A

14. PERMIT NO.
890
990 FNL ; 990' FEL
30-039-05079

15. ELEVATIONS (Show whether surface or bottom of hole)
**BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA**

5. LEASE DESIGNATION AND SERIAL NO.
CONTRACT No. 77

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
AXI Apache A

9. WELL NO.
4

10. FIELD AND POOL, OR WILDCAT
Ballard Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 16-23N-5W

12. COUNTY OR PARISH 13. STATE
Rio Arriba NM

RECEIVED

AUG 27 1986

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU. Pull tbg
- ② Bullhead 150 sxs class "B" cmt down 5 1/2" csg. Follow cmt w/34.2 bbls 9.2 ppg mud. This mud will sqz 50 sxs cmt into perfs. TOC @ ±1500'. Spot 100' cmt plug @ surface.
- ③ Cut off wellhead and install P&A marker. Clean location
- ④ Rig down. A P&A sketch is attached.

RECEIVED

SEP 12 1986

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

8-25-86

DATE

SEP 10 1986

AREA MANAGER
FARMINGTON RESOURCE AREA


*See Instructions on Reverse Side

NMOCC

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Farmington (6) File

P&A Marker includes:
 "AXI Apache A No. 4"
 "A-16-23N-SW"



Greg Ashdown

7/25/86

Copyrighted Inc.
 Circulation Sheet

Proposed P&A Sketch
 AXI Apache A #4

Ballard
 New Mexico