1 HLB

1 026

i lile

Form	
(May	1963
-	

UNITED STATES SUBMIT IN TRIPLICATE*
DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved,
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

OLOCOTONIC CONTRACTOR	DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY		SF-078272-A
OIL SUBJECT OF PREAD SAME 2. NAME OF OPPRATION BCO, Inc. 3. ADDRESS OF OPPRATION P. O. BOX 669 Santa Fe, New Mexico 87501 4. Incation of Will. Helport location clearly and in accordance with any State requirements.* See also square if below.) 1650' FSL & 1650' FEL 10-23N-7W NMPM 10-23N-7W 11. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, CR.) 7264 GR 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUP-OFF PELL OR ALTER CARNO NULL PERMIT OR ACCIDENT REPORT OF PARENTIN BULL (Cother) 17. ENTRY WATER SHUP-OFF PRACTICE TERATY OF PARENTIN AND SHUPPER CARNO NULL PERMIT NO. 18. ELEVATIONS (Show whether DF, RT, OR, CR.) 19. VIEL AND DE BAK, AND SHEET OR PARENTIN TO: TEST WATER SHUP-OFF PRACTICE TERATY OF PARENTIN TO: TEST WATER SHUP-OFF PRACTICE TERATY SHOW ADARDED AND ACCIDENTS AND NUMBER OF INTENTION TO: TEST WATER SHUP-OFF PRACTICE TERATY SHOW AND NUMBER OF PARENTIN WELL (Cother) 17. DESCRIPTION AND DEAD AND DEAD AND SHOW AND SH	Sl (Do not use	INDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Name of operation State of			7 UNIT AGREEMENT NAME
BCO, Inc. BCO, Inc. Address of operator P. O. Box 669 Santa Fe. New Mexico 87501 1. Inc. The operation of which (feboral location clearly and in accordance with any State requirement.* At surface 1650' FSL & 1650' FEL 10-23N-7W NMPM 10-23N-7W 11. BRC. T. N. M. OR BLA. AND STATE REPORT OF PARENT NO. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE TEST WATER SHOT-OFF PULL OR ALTER CASING MCLIFIEE CHAPLES HEAVE (SUPPLIES OF ALTERNA CASING MCLIFIEE CHAPLES HEAVE (SUPPLIES HEAVE) 17. DESCRIPTOR PROPOSED OR COMPLICATION OF ALTERNA CHAPLES HEAVE (SUPPLIES HEAVE) 18. PRATICAL TO ALTERNATIVE CASING MCLIFIES HEAVE (SUPPLIES HEAVE) 19. PRETATOR CASING MCM. ALTERNA CASING MCLIFIES HEAVE) 19. PRETATOR CASING MCM. ALTERNA CASING MCLIFIES HEAVE) 10. PRETATOR CASING MCM. ALTERNA	OIL GAS		T. CHI AGREEMENT NAME
3. ADDRESS OF OFERATOR P. O. BOX 669 Santa Fe, New Mexico 87501 1. Description of Weld. (Richgert location clearly and in accordance with any State requirements.* See also space 17 below.) 1650' FSL & 1650' FEL 10-23N-7W NMPM 16-23N-7W 17. DESCRIPTION ON TO: TEST WATER SHUT-OFF PRACTURE TREATMENT CHANGE PLANS CHAN			8. FARM OR LEASE NAME
P. O. Box 669 Santa Fe. New Mexico 87501 1. Accounts we will discount for the proper location clearly and in secondance with any State requirements.* 1650' FSL & 1650' FEL 10-23N-7W NMPM 16. If PERMIT NO. 16. ELEVATIONS (Show whether or, st. cs. etc.) 7264 GR 17. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER BIUT-OFF FULL OR ALTER CASING MICHIPLE COMPLETE ABANDON* CHANGE FLANS CHANGE FL	BCO. In	nc.	
A LOCATION OF WELL CHEPOT location clearly and in accordance with any State requirements. At surface 1650' FSL & 1650' FEL 10-23N-7W NMPM 16.	3. ADDRESS OF OPER	AATOR	
Lybrock Gallup 11. Sec. 21. M. of Bill. And 1650' FSL & 1650' FEL 10-23N-7W NMPM 10-23N-7W 11. SELEVATIONS (Show whether DF, RT, OR, etc.) 12. COUNTY OR PARISH 13. SYMPT 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHOT-OFF PRACTURE TREAT SHOOT ON ACHIEF OF MALTER CASING MULTIFLE COMPLETE ABANDON' SHOOTING ON ACHIEF OF MALTER CASING BEFAIR WELL (Other) (Other) (Other) (Other) 17. DEECHAR PROPOSED OR COUNTERED OFFERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of Starting at percence work. If well is directionally drilled, give subsurface locations and measured and tree vertical depths for all markers and somes per neut to this work.) 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca C1 and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-18-74 Placed well back in operation.	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)		
1650' FSL & 1650' FEL 10-23N-7W NMPM 10-23N-7W 11. FERNIT NO. 15. ELEVATIONS (Show whether OF, RI. GR. etc.) 7264 GR 10. 11. CHARLET NO. 12. COUNTY OK PARISH 13. SYATE Rio Arriba New Mexi NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: THEST WATER SHOT-OFF PELL OR ALTER CASING NULLTIPLE COMPLETE ABANDON' RECARD REPORT OF COMPLETE ABANDON' REPORT OR ACTIVED A REPORT OF COUNTERED OPERATIONS (Clearly state all perthent details, and give pertinent dates, including estimated date of starting are proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per next to this work.)* 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca C1 and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-17-74 12-18-74 Placed well back in operation.			Lybrook Gallup
16. FEL & 1650' FEL 10-23N-7W NNPM 10-23N-7W 11. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR. etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON'S CHANGE PLANS RIGOOT OR ACIDIZING X ALTERNOR CASING (Other) REPARK WELL (Other) 17. DESCRIPE IMPOSSIN OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting ar process work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-18-74 Placed well back in operation.			11. SEC., T., R., M., OR BLK. AND
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZED REPAIR WELL (Other) 17. DESCRIPE TRODUSED OR COMPLETED OFFERATIONS (Clearly state all pertinent details, and give subsurface locations and measured and true vertical depths for all markers and zones pertinent date. 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-18-74 Placed well back in operation.	1650'	FSL & 1650' FEL 10-23N-7W NMPM	10-23N-7W
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIPE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give subsurface locations and measured and true vertical depths for all markers and zones pertinent date. 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-18-74 Placed well back in operation.	14. PERMIT NO.		
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and cive pertinent dates, including estimated date of starting are proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per near to this work.) 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid. Swabbed to 12-17-74 12-18-74 Placed well back in operation.		7264 GR	Rio Arriba New Mexic
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting at proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid. Swabbed to 12-17-74 12-18-74 Placed well back in operation.	16.	Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data
PRACTURE TREAT MATER SHOT-OFF PRACTURE TREAT MULLIPLE COMPLETE SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIFE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting at proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca C1 and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid. Swabbed to 12-17-74 12-18-74 Placed well back in operation.		NOTICE OF INTENTION TO:	BSEQUENT REPORT CF:
SHOOTING OR ACIDIZING REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting at proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.) 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Placed well back in operation.	TEST WATER SH	UT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL X
REPAIR WELL (Other)	FRACTURE TREAT	MULTIPLE COMPLETE FRACTURE TREATMENT	
(Other) (Note: Report results of multiple exampletion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.	SHOOT OR ACIDIZ		G X ABANDONMENT*
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)* 12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7.1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7.1/2% acid. Swabbed to 12-17-74 12-18-74 Placed well back in operation.		(Note: Report r	esults of multiple completion on Weil
12-9-74 Set plug at 5239'. Found hole at 4450' Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.		(Clarify the coll portional details and give portional	dates including estimated date of starting any
Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.	proposed work	k. If well is directionally drilled, give substitute locations and measured and true	vertical depths for all markers and zones perti-
Set Guiberson 4 1/2 packer at 4250 and squeezed with 2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.		50001 Read halo at 4/501	기 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기
2% Ca Cl and 113#'s analad-9. 12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7.1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7.1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.	12-9-74	Set plug at 5239°. Found note at 4450	with
12-10-74 Drilled approximately 90 feet of cement and tested casing to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7.1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7.1/2% acid. Swabbed to 12-17-74 12-18-74 Placed well back in operation.		2% Ca Cl and 113#'s analad.9.	
to 1000#'s for 15 minutes. 12-12-74 Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.			
12-12-74 Spotted 500 gallons 7.1/2% acid. Swabbed to 12-15-74 12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.	12-10-74	Drilled approximately 90 feet of cement and test	ed casing
12-15-74 Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74 12-18-74 Placed well back in operation.		to 1000#'s for 15 minutes.	
12-18-74 Placed well back in operation.	12-12-74	Spotted 500 gallons $7.1/2\%$ acid. Swabbed to 12-	15-74 A TABLE TO SEE THE SECOND SECON
EPEIVED	12-15-74	Spotted 1000 gallons 7 $1/2\%$ acid Swabbed to 12-	·17-74
CEPTIVED WAR 23 1974 COM.	12-18-74	Placed well back in operation.	
war 23 com.		CECFIARD 1814	
$\left(\begin{array}{cc} 0 & 0 \\ 0 & 0 \end{array}\right)$		MAR CON. 3	

18. I hereby certify that the foregoing is true and correct		
SIGNED LASSY DELLE	TITLE President	DATE March 18, 1974
(This space fee l'ederal or State office use)		
APPROVED BY	TITLE	DATE