


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. SP-078494-A

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS **RECEIVED**

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>DEC 27 1962</u>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL <u>X</u>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 27, 1962

Yarborough-Federal

Well No. 1 is located 1840 ft. from N line and 1840 ft. from E line of sec. 3

SE 1/4 of Sec. 3
(1/4 Sec. and Sec. No.)

23-N
(Twp.)

OW
(Range)

101PM
(Meridian)

Undesignated
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6709 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has reached its economic limit and is now operating at a loss. Since there are no prospects of returning this well to a commercial producer, we propose to plug the well as follows:

Spot 25 sacks cement plug over perforations 5440' to 5485' and 10 sack plug in top of 5 1/2" casing. Cut off well head and weld 4" pipe marker in top of 5 1/2" casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXACO Inc.

Address Box 310

Farmington, N. M.

By C. P. Farmer

Title Dist. Supt.

