

Form 3-331a  
(Feb. 1951)

Section 5


(SUBMIT IN TRIPPLICATE)

Land Office Santa Fe

Lease No. W-03993

Unit Gardner-Federal

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 6, 1958

Gardner-Federal  
Well No. 1 is located 1055 ft. from N line and 993 ft. from W line of sec. 5


Section 5 (1/4 Sec. and Sec. No.) 23-N (Twp.) 1-E (Range) H. M. P. S. (Meridian)  
Undesignated loc. Cliff Pool (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7715 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 3470' of 5 1/2" Liner on bottom at 3470' with 200 sz cement.  
Then temperature survey top of cement at 3250', outside 5 1/2" Liner and 3419' inside 5 1/2" Liner. Tested 5 1/2" Liner with 1900 lbs for 30 minutes before and after drilling plug. Tested OK no break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MARSHALL PETROLEUM COMPANY

Address P.O. BOX 633

ALBUQUERQUE, TEXAS

By Harve H. Taylor  
Title Division Superintendent

