


Section 5

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. 2-03773Unit Gardner-Pole

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	☒
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 6, 1958

Gardner-Federal
Well No. 1 is located 1055 ft. from N line and 293 ft. from E line of sec. 5


Section 5 (1/4 Sec. and Sec. No.) 23-N (Twp.) 1-E (Range) 10-11-58 (Meridian)
Undesignated (Field) ic. Cliff Pool (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7715 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 3470' of 5 1/2" Liner on bottom at 3470' with 200 sz cement.
Run temperature survey top of cement at 3250', outside 5 1/2" Liner and 3419'
inside 5 1/2" Liner. Tested 5 1/2" Liner with 1500 lbs for 30 minutes before and
after drilling plug. Tested at no break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 2-03773Address P.O. Box 633Albuquerque, N.M.By Harold W. MayfieldTitle Division Superintendent

