Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATE* (Other instructions on re-	Form approved. Budget Bureau No. 42-R1424.	
•	DEPARTMENT OF THE INTERIOR	OR verse side)	5. LEASE DESIGNATION AND SERIAL NO.	
	GEOLOGICAL SURVEY		CONTRACT NO.39	
	NDRY NOTICES AND REPORTS C		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	s form for proposals to drill or to deepen or plug ba Use "APPLICATION FOR PERMIT—" for such pro	ick to a different reservoir.	JICARILLA APACHE	
OIL GAS WELL WELL	<b>X</b> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR	^ _		8. FARM OR LEASE NAME	
CONTIA	KENTAL OIL CON	PANY	AXI APACHE"C"	
3. ADDRESS OF OPERATO		C/21/-	9. WELL NO.	
BOX 40	O, TTOBBS, N.N.	88240	10 100 100 100 100 100 100 100 100 100	
See also space 17 bel At surface	Report location clearly and in accordance with any S low.)	state requirements.	10. FIELD AND POOL, OR WILDCAT	
		( C > B)	9LLARD STCTURED CLIFFS 11. SEC., T., R., M., OR BLK. AND	
990'F	NC & 990'FWL 0.	1 SEC. 5	SURVEY OR AREA	
	<b>A</b> 111111	1	SEC 3 TOOM DELL	
14, PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OF PARISH 13. STATE	
	6697' DF		RIO ARRIBA N.M.	
16.	Check Appropriate Box To Indicate No	ature of Notice, Report, or O	ther Data	
	NOTICE OF INTENTION TO:	SUBSEQU	SUBSEQUENT REPORT OF:	
TEST WATER SHUT-	OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	· (Other)		
(Other) ADD	YERFS & STIMULATEX		of multiple completion on Well tion Report and Log form.)	
17. DESCRIBE PROPOSED (proposed work. I nent to this work.)	OR COMPLETED OPERATIONS (Clearly state all pertinent if well is directionally drilled, give subsurface location	details, and give pertinent dates, ons and measured and true vertical	including estimated date of starting any depths for all markers and zones perti-	
Prac 2	フルー・ココ コーノ・・・/フ コ	repr c	D 1- +	

PERF 2316-2328' W/Z-JSPF. SET PKR. AT ±2290'.

SPOT 200 GALS. 15% HCL W/ADDITIVES.

FRAC W/13,550 GALS. FORM, 13,500 LBS. SAND,

3,400 GALS. WATER & 150,000 SCF NZ.

POOH W/TBG. & PKR. RUN 11/4" TBG. & SWAB WELL TO PRODUCTION.

AUG 9

SIGNET SIGNET SIGNET STATE OF THE SIGNET SIG	TITLE ADMIN. SUPV.	DATE 8-5-76
(This space for Federal or State office (Se)		And the state of t
APPROVED BY	TITLE	DATE

Ollal

\*See Instructions on Reverse Side