- 1 NCRA
- 1 File

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well	Notice of to Drill	DE INTENTION DEEPER	
Notice of Intention to Plug Well	x	Notice of Intention to Pluc Back	Notice of to Set L	of Intention iner	
Notice of Intention to Squeeze		Notice of Intention to Acidize		of Intention T (Nitro)	
Notice of Intention o Gun Perforate		Notice of Intention (Other)	Notice of (Other)	P Intention	
DIL CONSERVATION CON SANTA FE, NEW MEXICO	MISSION	Albuquerque, (Piñce)	New Mexico	April 28, 1	961
Gentlemen:					
Following is a Notice of	Intention to d	o certain work as described below	at the		
al R. Reese & Ass	ocInc	Reyno	oldsWell No	1 -2 in	<u>A</u>
E	f Sec	Reyno 12 , T 23N , R 6W	, NMРМ.,	ldcat	Poo
io Arriba	Co	ounty.			
		LL DETAILS OF PROPOSED IN THE RU			
5600'. Pull 4-1/ lesaverde formation from 2210 from 197' to 160' &	(FOLLOV) sx plug 2" casing in from 3)' tp 227(·	ations. Plug wi 5000'. Spot 50 0 sx plug across bottom of 8-5/8	ill be from 5900' sx plug across Pictured Cliffs 3" surface casing	
5600'. Pull 4-1/ lesaverde formation from 2210 rom 197' to 160' &	(FOLLOV) sx plug 2" casing in from 3)' tp 227(across Gallup perfors from approximately 800' to 3950'. Spot 2	ations. Plug wi 5000'. Spot 50 0 sx plug across bottom of 8-5/8	ill be from 5900' sx plug across Pictured Cliffs " surface casing arker & abandor MAY1 1961 OIL CON. COM	
esaverde formation from 2210 from 197' to 160' & ell.	(FOLLOV Sx plug 2" casing n from 3 0' tp 227(10 sx plu	across Gallup perform from approximately 800' to 3950'. Spot 20'. Spot 10 sx plug in a in top of surface can	ations. Plug wi 5000'. Spot 50 0 sx plug across bottom of 8-5/8 sing. Install m	ill be from 5900' sx plug across Pictured Cliffs " surface casing arker & abandor MAY 1 1961	
Approved. MAY 1 1961. Approved. MAY 1 1961. Approved. MAY 1 1961.	(FOLLOV) sx plug 2" casing in from 3)' tp 227(10 sx plu	across Gallup performs from approximately 800' to 3950'. Spot 20'. Spot 10 sx plug in ag in top of surface can be surfaced as a	ations. Plug wi 5000'. Spot 50 sx plug across bottom of 8-5/8 sing. Install m	MAY 1 1961 OIL CON. COM DIST. 3 Associates, Inc.	
5600'. Pull 4-1/ lesaverde formation ormation from 2210	(FOLLOV) sx plug 2" casing n from 3) tp 227(10 sx plug	across Gallup performs from approximately 1800' to 3950'. Spot 20'. Spot 10 sx plug in ag in top of surface can be surfaced by 19	ations. Plug wi 5000'. Spot 50 sx plug across bottom of 8-5/8 sing. Install m	MAY1 1961 OIL CON. COM DIST. 3 Associates, Inc.	Jones