1200 SECURITY LIFE BUILDING DENVER, COLORADO 80202



TELEPHONE 303 - 629-1050

January 23, 1976

Lynco Oil Corporation #2 Denver Tech. Center 7890 E. Prentice

Englewood, CO 80110 Re: Regina #5-Hole Deviation

Gentlemen:

The following deviation tests were taken during the drilling of the subject well:

<u>Depth</u>	Deviation
60 <b>'</b>	1/4 degree
530	1/2 "
1010	1 "
1584	1 "
2160	1 "
2578	3/4 "
3024	1 "
3254	1 "

Total Depth 3254'

Very truly yours,

SIGNAL OILFIELD SERVICE, INC.

L. F. Stone

President

Colorado	)
Denver	) ss. )
	<u>ry</u> , 1976.
Thron	y K. Hecco
Nota	ry Public
	Thie

My Commission Chysics (Let. 20,5007)

