F	`orm	9-331
ŧ	May	1963)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on re-

MULTIPLE COMPLETE

CHANGE PLANS

Form approved.

	Bua	cet		0. 42-H	
5. LEASE	DES	IG N A			

ALTERING CARING

ABANDONMENT*

THE THE THIE BUT	O. BEARD PRINTING AND BERTED NO.
GEOLOGICAL SURVEY	Jicarilla Joint Venture
OTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME

CHINDRY MOTIC	ES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR THIBE NAME
(1)0 not use this form for proposals	to drill or to deepen or plug back to a different reservoir. ON FOR PERMIT—" for such proposals.)	Jicarilla Apache
OIL GAS OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Odessa Natural Corpo 3. ADDRESS OF OPERATOR	ration	8. FARM OR LEASE NAME Jicarilla Jt. Venture "PC" 9. WELL NO.
P. O. Box 3908, Odes Location of Well (Report location clean See also space 17 below.) At surface 1700 FNL, 1600 FEL	Sa. Texas 79760 rly and in accordance with any State requirements.*	105 10. FIELD AND POOL, OR WILDCAT Ballard Pictured Cliffs 11. SEC., T., E., M., OR BLE. AND Sec. 4-123N-R3W N. M. P. M.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7157 G. L., 7162 D. F., 7163 KB	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
18. Check Appr	opriate Box To Indicate Nature of Notice, Report, or C	<u>'</u>

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

7-13-78 T. D. 3160' Plug and Abandon. Set cement plugs:

TEST WATER SHUT-OFF

FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

3100'-3000', 100', 30 sacks 2770'-2570', 200', 50 sacks 625'- 525', 100', 30 sacks 175'- 125', 50', 20 sacks

Set dry hole marker at surface with 15 sacks cement in top of surface casing.

For: Odessa Natural Corp	orati	on
18. I hereby certify that the foregoing is true and correct SIGNED Walch D D	TITLE _	President, Walsh Engr. & Production Corp. DATE 7/14/78
This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _	RECLEIVED

JUL 1 9 1978