

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☒ Dry Hole

2. NAME OF OPERATOR  
Robert L. Bayless

3. ADDRESS OF OPERATOR  
P.O. Box 1541, Farmington, NM 87499

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1630' FNL & 1690 FEL  
AT TOP PROD. INTERVAL: same  
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

RECEIVED  
DEC 16 1982

U.S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE  
Contract 78

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Jicarilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
AXI "F" Apache

9. WELL NO.  
7

10. FIELD OR WILDCAT NAME  
Ballard Pic. Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 11, T23N, R5W

12. COUNTY OR PARISH  
Rio Arriba

13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6794' G.R.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-14-82 Blew well down and removed wellhead. Rigged up Cementer Inc. Filled 2-7/8" EUE casing with water, followed by 40 sacks of Class "B" cement mixed with 5 Bbls of water, followed by 3.5 Bbls of water, followed by 10 sacks of Class "B" cement mixed with 1.2 Bbls of water. Rigged down Cementers Inc.

1 - 40 sx. plug placed at 2424'-999'  
1 - 10 sx. plug placed at 363'-surface  
Both plugs were Class "B" cement

12-15-82 Installed a dry hole marker, and filled-in reserve pit.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED Robert L. Bayless TITLE Operator DATE 12/16/82

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY.

APPROVED  
AS AMENDED

DEC 07 1984

M. MILLENBACH  
AREA MANAGER

\*See Instructions on Reverse Side

NMOCC

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.