

Jic. Cont. 575 (CC)
3162.3-1(1) (916)

Caller Service 4104
Farmington, New Mexico 87401

FEB 21 1986

CERTIFICATE--REALLY REQUESTED

H. P. Martin and Associates, Inc.
700 N. Butler
Farmington, NM 87401

Certified:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. No. 38 Martin Whitaker, NW sec. 15, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 398.

2. No. 39 Martin Whitaker, NW sec. 15, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 398.

3. No. 40 Martin Whitaker, SW sec. 15, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 398.

4. No. 41 Martin Whitaker, SE sec. 15, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 398.

5. No. 36 Martin Whitaker, NE sec. 16, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 398.

6. No. 37 Martin Whitaker, SE sec. 16, T. 23 N., R. 4 W., Rio Arriba County, New Mexico, Jicarilla Contract 398.

As discussed with Mr. Jim Abney of your Company on February 12, 1986, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

FEB 24 1986

ABANDONED LOCATION

Call Service 4104
Farmington, NM 87401

J

30-039-23509

7-27-84


F. loc.	1850/S;	1650/W	Cu. ft.	Elev.	7219	GL	Spd.	Cu. ft.	Comp	ID	Cu. ft.	P8
Casing S.	@	w	Sx.	Int.	@	W	Sx.	Pr.	@	W	Sx.	@
Csg. Perf.								Prod. Slim.				
I.P.	BO/D	PSI After	Hrs.	SICP	PSI After	Days GOR	Grav.		1st Del.	Gas		
MCF/D	Aftr											
TOPS	NID X			Well Log								
Ojo Alamo	C-103			Plot X					Schd.			
Kirtland	C-104			Electric Log					PC			
Fruitland					C-122				Q			
Pictured Cliffs				Dtr					PW			
Chacra				Dar					PD			
Cliff House									D			
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												
									Acres	40		

P

Lin. Gal-Dak Co. RA S 15 1 23N R 4W U K Ober. W.B. Martin & ASSOC. Inc. Martin-Whittaker No. 40

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,


for Mat Millenbach
Area Manager

Enclosures

cc:
NMOCC

Martin-Whittaker #40

K-15-23N-4W

W.B. MARTIN & ASSOCIATES

FEB 24 1985