

United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area

1235 Laplata Highway Farmington, New Mexico 87401



IN REPLY REFER TO:

SF-078362 et al. (WC) 3162.3-1.0 (019)

NO.1 4 1081

NOVI 5 1991
OIL CON. DIV

Jack A. Cole PO Box 191 Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. No. 34 Rincon, Sec. 17, T. 23 N., R. 6 W., Rio Arriba County, New Mexico, lease SF-078359.
- 2. No. 6 Rincon, Sec. 5, T. 23 N., R. 6 W., Rio Arriba County, New Mexico, lease SF-078362.

The subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

[s] John L. Keller

John L. Keller Chief, Branch of Mineral Resources

2 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONE LC. TION

asing S@ ig.Perf.	Sx. Int	lev. 6933 GL Spd. Cu. ft. Qu. ft. Prod. Stim	@—	\	w	Sx. T		_@	↑ Gas
BO/D MCF/D AI	iterHrs. SICP	Grav PSI_After Days GOR					µ		Ñ \$
TOPS	NITD X	Well Log	TEST DAT	Α	,			, -	
Cjo Alamo	C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland	C-104	Electric Log					<u> </u>		
Fruitland		C-122							<u> </u>
Pictured Cliffs	Ditr	Dfa							
Chacra	Datr	Dac							
Cliff House							Ţ		
Menefee									
Point Lookout	,								
Mancos									
Gallup									
Greenhorn									
Dakota									
Entrada								<u> </u>	
		Acres 40				T			

Rincon #34

K-17-23N-06W

JACK A. COLE