Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	SUBMIT IN TRIPLICATE* (Other instructions on re- verse side)	SE-078272 •	31. 1985 IND SERIAL NO.
SUN (Do not use this	DRY NOTICES AND REPORTS Of form for proposals to drill or to deepen or plug bath use "APPLICATION FOR PERMIT—" for such pro-	NEWELLS ck to b different reservoir. possis.)	6. IF HIDIAN, ALLOTTER	OR TRIBE NAME
OIL X GAB	OTHER	AN 11 PH 12: 54	7. UNIT AGREEMENT NAM	t B
2. NAME OF OPERATOR		RHINGTON, N.M.	8. FARM OR LEASE NAME	6
BCO, Inc			Dunn •	
3. ADDRESS OF OPERATOR			9. WELL NO.	
135 Grant, Santa Fe, NM 87501 ·			3-Y ·	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Undes. Graneros Lybrook Gallup 4 11. SEC. T. R. M., OR RLK. AND	
2280 FSL and 780 FEL.			SURVEY OR ARBA	
			Sec 3, T23N	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISE	
	GL 6978' •		Rio Arriba	NM •
PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17 DESCRIBE PROPOSED Of proposed-work. If	TEST WATER SHOT-OFF PULL OR ALTER CASING PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL OIL ON. GRANDON* GOTHER PLANS OCTOBER PROPERTY PROPERTY.		s of multiple completion on Well pletion Report and Log form.)	
01/02/	91 Advised Belva Christen intended to spud the w we intended to cement on January 2, 1991.	ell January 2, 19	91 and that	
	Spudded well. Drilled joints, 348' 24# 8-5/8 pipe. DV 3/4° at 363' cemented with 250 sack 1/4 lbs flocele per salbs with a yield of 1. total of 295 cubic feed Plug down 11:30 p.m. Mixed 100 sacks of Clalbs flocele per sack multiple 1.18 cubic feet or a total control of 295 cubic feet or a total cubic feet o	" limited service . Landed pipe at s Class B 2% CaC1 ck. Cement was m 18 cubic feet per et. (About 53 bar Did not circulate ss B 2% CaC1 ceme ixed at 15.6# wit cotal of 118 cubic Tagged cement at	surface 360' and cement with nixed at 15.6 sack or a crels slurry) cement. ent with 1/4 ch a yield of c feet. 30' with 1 cubic feet	

18. I hereby certify that the foregoing is true and correct

SIGNED Eugabella B. Hosshar Title President.

(This space for Federal or State office use)

APPROVED BY TITLE FARMINGTON RESOURCE AREA

BY

job finished 7:00 a.m.

*See Instructions on Reverse Side

A CAROLON

Operator: BCO, Inc.

135 Grant Avenue Santa Fe, NM 87501

SUNDRY NOTICES AND REPORTS ON WELLS

Lease No.: SF-078272

Page Two

01/03/91 Called Steve Mason at BLM. Told him method we had used to repair cement job. He gave retroactive verbal approval to proceeding with repair. Waited for cement to set until 5:45 p.m. Tested casing at 1000# for 30 minutes. Casing held. Copy of Halliburton job log is attached..

FROM HALLIBURTON FMN, NMRECEIVED PAGE. E JAN 8 '91 14:42 PAGE.001 HALLIBURTON SERVICES JOB LOG CUSTOMER BCD 85/8 Swiffee 11 P1112:5 FORM 2013 R-2 019 FARITHE TON, N.M. FUMPS PRESSURE (PSI) CHART NO. RATE (BPM) on Location, Rig up, Safety media 2100 50 Begin pumping water AHEAD 2300 4 10 ED START MIXING & DUMPING CEMENT MIXED @ 1510# 19AL 2305 52,5 CEMENT Complete SHUT DOWN 2322 Drop plus 50 Begin Displacement 215 2325 DIDNOT CIRCULATE ANY CEMER 2330 wait on more cenent Pump water AHEAD TO BREAK ルス 0630 circulation Bogin mixing cement @15.6#/gac Pumping Down 1141 Tubing 10.5 2633 arculating GOOD CEMENT 0645 CHASE with water to CLEAR 0646 our lines SAUT DOWN, Job complete 0650 THANKS im & OREL