Submit 3 Copies to Appropriate
District Office

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico nergy, Minerals and Natural Resources Departme

Form C-103

Butto oute			•		Re	evised 1-1-89	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA	TION	DIVISION	WELL API NO			
2040 Pacheco				30-039-26645	•		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe,	NM 8750	05	5. Indicate Ty	pe of Lease		
P.O. Drawer DD, Artesia, NM 88210	,			- 2,	STATE	] FE	ΞΠ
DISTRICT III	0			6. State Oil &	Gas Lease No.	<del></del>	
1000 Rio Brazos Rd., Aztec, NM 8741				E-1207-8			
SUNDRY NOTIC	ES AND REPORT	rs on i	WELLS				
(DO NOT USE THIS FORM FOR PO				7. Lease Name	e or Unit Agreement	Name	
l .	RVOIR. USE "APPLICATION C-101) FOR SUCH PROPOSA	7.					
1. Type of Well:	3-101/1 010 000111 1001 002		No.	State 16			
OIL GAS		$\ker_T$	SEP 2001	Searc 10			
WELL X WELL	OTHER	•		193			
2. Name of Operator			Ch. Cont Off	8. Well No.			
Elm Ridge Resources, Inc.			6925, \$	#4./			
3. Address of Operator				9 Pool name			
PO Box 189 4. Well Location			<del> </del>	Counselors Ga	llup Dakota	<del></del>	
1	)20 Th	Courth	T.	1725	n .n .m	777	
Offit Letter N	eet From Th	South	Line and	1735	Feet From Th	West	Line
Section 16	Townshi 23N R	ange 6W		NMPM		Rio Arriba	a County
	10. Elevation	Show whe	ther DF, RKB, RT,	GR, etc.)			
		6880					
Check A	appropriate Box to	Indicat	te Nature of N	Notice, Report	, or Other Dat	a	
	NTENTION TO:		1	=	NT REPORT		
		-			_	• • •	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	₹K [	ALTERING CA	SING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND AB	ANDONMENT	· 🔲
PULL OR ALTER CASING			CASING TEST A	ND CEMENT JO			
OTHER: Drilling		x	OTHER:				
12. Describe Proposed or Completed Operation	ıs (Clearly state all pertinent deta	ils, and give p	nertinent date, including	estimated date of starting	ng any proposed		
work) SEE RULE 1103.	1/41 1			<b>.</b>			
Spud well 7/28/01. Drilled 12-							
w/250 sx Class "B", 3% CaCl, 1				-			
surface. Drilled 7-7/8 to 5650'							
KB. Stage tool set @ 2313' KB							
sx Class "H", 1% CaCl, 1/4# Fl							
2nd stage w/395 sx 65/35/POZ,	<del>-</del>		-		110		
stage tool w/2000 PSI - plug hel	d. Circulate 10 bbls to	surface.	Rig down cemen	iters. Set slips. (	Cut off casing. Re	lease rig.	
Install wellhead.				•			
Certified Return Receipt # 7000	1670 0010 0494 0407						
I hereby certify that the information ab		best of my l	knowledge and belief.				
SIGNATURE MUCH	Mubelnik	· · · · · · · · · · · · · · · · · · ·		duction Technicia	n DATE	09/21/0	1
TYPE OR PRINT NAME TYPE	dy Grubelnik				TELEPHONE NO. 50	5-632-3476	ext. 201
(This space for State Use) GRIGINAL 1	IGNEO BY OHAMLET F	<b>PAN</b>	And	A GVZ IM2	PECTOR, DIST. #3	CED 9 c	2004
APPROVED BY			TITLE		DATE	<b>SEP</b> 2 6	ZU01
					DAIE		