


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Wichita Falls  
Lease No. 15 00361 A  
Unit                     



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 23, 1960

**Clyde B. Harvey**

Well No. 1 is located 1520 ft. from N line and 2340 ft. from E line of sec. 21

NE 1/4 SW 1/4 21 18 N 34 S. M. P. M.

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

W. C. S. Mineral New Mexico


(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~driller's~~ driller's floor above sea level is 6740 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Sup report of perforating  
4 - Stalloy jet shots per ft. from 992' to 1000'  
(32)  
Frac w/ 3/8" bbls. oil and 20,000 lbs. sand  
Max. T. P. 800#  
Inj. rate 42 bbls.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Francis L. Harvey  
Address P. O. Box 990  
Wichita Falls, Texas

By [Signature]  
Title Agent

