


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe
Lease No. 0760
Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 200 ft. from [N] line and 600 ft. from [E] line of sec. 14
SE 1/4 Sec. 14 T1N R1E NM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
United Sandoval County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7133 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 13-1/4" hole to 300' -- Set 4-1/2" casing at 287' with 150 sacks.
Drilled 9-7/8" hole to 4080.' Set 5-1/2" at 4057' with 150 sacks. Drilled
with air to 5414.' Filled hole with mud. Prep. to pull 5-1/2" casing. Prepare
to set 25 sacks plug at base of casing, set 25 sack plug on top of sub of 5-1/2"
casing. set 25 sack plug at base of surface pipe and 5 sack plug with dry hole
marker at the surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ray Furr
Address Pox 1650
Lubbock, Texas

By Harrell Budd
Title Consulting Geologist