UNITED STATES

May 1963)	DEPARTM	IENT OF THE INTER	RIOR (Other instructions on re	5. LEASE DESIGNATION AND SERIAL NO.
	DLI ARTIN	EOLOGICAL SURVEY		165 🗗 🗒 👼
			ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
S	UNDRY NOTI	CES AND REPORTS	ON WELLS	Jicarilla & Bal
. (Do not use	this form for proposa Use "APPLICA"	als to drill or to deepen or plug TION FOR PERMIT—" for such	proposals.)	Jicariiia
1.				7. UNIT AGREEMENT NAME
OIL GA				2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
WELL WE				8. FARM OR LEASE NAME
		Gas Company, Inc.		R No. 165
3. ADDRESS OF OPER		9. WELL NO.		
3. ADDRESS OF 0121	pidolea Bank	1 3 1		
1008 Ridglea Bank Building, 6300 Ridglea Place 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIELD AND POOL, OR WILDCAT
See also space 1	7 below.)	So. Blanco P.C.		
At surface	from North li	11. SEC., T., R., M., OR BLK. AND :: -		
990	IIOm Norem II	SURVEY OR AREA		
				28 - 23N - 2W
14 270415 10		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
14. PERMIT NO.		GL7485.78'		Sandovál New Mexico
		<u> </u>		
16.	Check Ap	propriate Box To Indicate	Nature of Notice, Report, or	Other Data 돌충을 - 출 돌충물炎
	NOTICE OF INTEN	TION TO:	SUBSEC	QUENT REPORT OF E
			WARD SHEET OF	REPAIRING WELL
TEST WATER SE	" T = 1" ——	PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	
FRACTURE TREA	· -	MULTIPLE COMPLETE X	SHOOTING OR ACIDIZING	ABANDONMENT®
SHOOT OR ACIDI		ABANDON*	_	
REPAIR WELL		CHANGE PLANS	(Other)	ts of multiple completion on Well
(Other)			. T. D	pletion Report and Log form.)
17. DESCRIBE PROPOS	SED OR COMPLETED OPE	RATIONS (Clearly state all perting mally drilled, give subsurface lo	ent details, and give pertinent date cations and measured and true verti	s, including estimated date of starting any cal depths for all markers and zones perti-
nent to this w	ork.) *			
7.1	- 1 d abanda	and April 29 1976	(see attached invoice	extend of the content
Plugg	ged and abando	oned April 20, 20.0	(222	the Processing of the Processi
-1	1 1	on and surface rest	ored.	CE TOMBONE THE BUILD OF THE BUI
Clean	ied up locatio	Jii and Surface rest		
				orepaints To Experience To Experie
				医二甲基甲酰氰合物 医多形形式
				그
			Carlo Carlo	그의 시민들을 통해 교회 교회원인
				(ROME) 기술유발표립 등을 모임경임
		•	1 20,000	[S / 사진통유원 관리 및목상임
			1 21/2 2/37	
			111 2	
			010	
			- Maria para	<u> </u>
18. I hereby certif	y that the foregoing i	s true and correct		DATE 6/28/77
arayme /	ul1)-13.	TITLE_	Treasurer	DATE 6/28/77 -
SIGNED				
(This space for	r Federal or State off	ice use)		Course Have a
	-	TITLE		DATE
APPROVED B	OF APPROVAL IF			

Office: 325-1271

BEDFORD INC.

Home: 325-3361

P. O. BOX E

FARMINGTON, NEW MEXICO 87401

May 1, 1976,

Trans Delta Oil & Gas Company, Inc. 1008 Ridglea Bank Building 6300 Ridglea P. Ft. Worth, Texas 76116

INVOICE

For plug and abandonment of your Jicarilla R-3 located in NW/4 Sec 28 T23N, R2W as follows:

Rig Time

4-26-76	Move in & Spot equipment 9 hours @ 56.00			
4-27-76	Dig deadman hole, bury anchors, Rig up, Pick up tbg, spot 15 sx plug from 3140' to 3020', Pull tbg out of cement.	672.00		
	12 hours @ 56.00	0/2.00		
4–28–76	Finish pulling tbg, Strip down well head to 4 1/2 slips. Set hydrolic jacks. Work casing, Casing stuck @ 525', shot csg off @ 522', Pulled casing. Load out Hydraulic jacks. Ran 2" tbg to stub. 1 hour HRTCH 11 hours @ 56.00	616.00		
	Ti Hours @ 30.00	010.00		
4-29-76	Spot 50 Sx plug @ stub, Pull tbg to 125', Spot 15 Sx plug @ 125' to 75' cut well head off, Install P&A Marker w/10 Sx surface plug. 8 hours @ 56.00	448.00		
Pump Truck	Service			
Fullip IT dek	Jei vice			
4-27-76	Spot 15 Sx plug 3140' to 3020'	200.00		
4-29 - 76	Spot 50 Sx plug @ Stub	200,00		
	Spot 15 Sx plug @ 125'	200.00		

Electric Wireline Service

4-28-76 Shot 4 1/2 csg off @ 522'

Casing Pulling Service

4-28-76 Pulled 522' 4 1/2 csg @ .30/ft 156.60

Winch Truck & Float

4-26-76 Haul Hydraulic jacks to loc

5 hours @ 18.00 90.00

Power Tong Rental

2 days @ 60.00 <u>120.00</u>

\$3356.60

150.00

4% State Tax 134.26 / \$3490.86



