Form	9-881 a
(Feb	. 1951)

`-		 	
	Ж	 	
1		 	
		 1	ĺ

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Offic	. Farmington, N.M.
Lease No.	SF 078361

CEIVED

JAN 1 4 1959

SUNDRY NOTICES AND REPORTS ON WELLSLOGICAL SURVEY

			WEN MEX
	TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION	TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
	TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTIO	TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTIO	N TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTIO	N TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION	N TO ABANDON WELL		
	(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)	
		January 20,	, 19_58
		(Range) (Meridian)	ec. 23
Mi lagar	Sando	or Subdivision) (State or Territory)	
(Field)	County	Ot principles	
he elevation of	the derrick floor above sea le	vel is 71.34 ft. ILS OF WORK	
		zes, weights, and lengths of proposed casings; indicate mudding other important proposed work)	g jobs, cement-
	and the second s		
-5/8' sur	face casing comenten	3 \$ 206' w/200 sacks.	Control of the Contro
	face casing cemented gs were spotted as		
cement plu	gs were spotted as	follows:	
Cement plu	gs were spotted as : 5360' - 5580'	follows:	1959
cement plu 65 sx 30 sx	gs were spotted as : 5360' - 5580' 4250' - 4350'	follows:	1959 COM
Cement plu 65 sx 30 sx 45 sx	gs were spotted as 1 4250' - 4350' 2000' - 2150'	follows:	1959 com.)
Cement plu 65 sx 30 sx	gs were spotted as 3 5360' - 5580' 4250' - 4350' 2000' - 2150' 550' - 700'	follows:	1959 com
Cement plu 65 sx 30 sx 45 sx	gs were spotted as 1 4250' - 4350' 2000' - 2150'	surface casing	1959 com.)