

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

WM 0551833-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pan American "C" USA

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR B.L. AND
SURVEY OR AREA

**NE 1/4 NE 1/4 Section 17,
T-28-N, R-3-E**

12. COUNTY OR PARISH

Sandoval

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☐ OTHER **Wildcat**

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

P. O. Box 480, Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FHL & 1980' FHL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

ADD 6816'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As a result of failing to find commercial quantities of oil or gas in the subject well, we plugged and abandoned the well as follows:

1. Spotted 40 sacks cement plug from 9200' to 9100'.
2. Spotted 40 sacks cement plug from 7450' to 7330'.
3. Spotted 40 sacks cement plug from 6450' to 6350'. (9-5/8" C&A 6370'.)
4. Cut and pulled 9-5/8" casing at 1555'.
5. Spotted 60 sacks cement plug on top of 9-5/8" casing stub, from 1595' to 1515'.
6. Spotted 60 sacks cement plug from 1110' to 1030' (13-3/8" C&A 1072').
7. Spotted 20 sacks cement plug from 20' to surface.
8. Erected F&A marker and cleaned up location.

Plug and abandonment completed May 18, 1967.

RECEIVED

MAY 22 1967

**U. S. GEOLOGICAL SURVEY
FARMINGTON, N.**

18. I hereby certify that the foregoing is true and correct.

SIGNED

G. W. Eaton, Jr.

G. W. Eaton, Jr.

(This space for Federal or State office use)

TITLE

**OIL CON. COM.
DIST. 3**

Area Engineer

DATE

May 19, 1967

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.