January 31, 1969

Mr. Jerry W. Long
District Engineer
G. S. Department of the Interior
Geological Survey
G. O. Box 1809
Charango, Colorado 81301



ear Fr. Long:

This is in response to your notice relative to the Jicarilla No. 368 and Jicarilla A-55, well 45.

ince the plugging of the Jicarilla 300, we have been mable to get to the location for the series of installing the dry hole marker. The location was levelled, but the dry hole marker was not ready, and was, therefore, not installed at that time.

As soon as we are able to get to the location, the dry hole marker will be installed.

The weather is such that it is not possible to level the abandoned location on the dicarilla 4-55, well 45. Orders have been issued to level the location as soon as the contractor has equipment in the area and weather permits.

then the work set forth above as been an exposed will be notified.

Carry Gardin St.

ti i i granda da karanta da karan