

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Contract 373

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cuba Pon Am

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Five Lakes Ch.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

24-T22N-R3W-N4PM

12. COUNTY OR PARISH 13. STATE

Sandoval

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Refiners Petroleum Corporation

3. ADDRESS OF OPERATOR

1223 Bank of New Mexico Bldg., Albuquerque, NM 87102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' fsl & 1650 fwl

14. PERMIT NO.

USGS 10-28-70

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7246 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Plan to P & A with the following procedure:

Drill bridge plug at 6300' and set the following cement plugs;

1. 6730 to 6850 (Lk & Gr) 120'-11 sxs

2. 5510 to 6050 (Gp) 540'-55 sxs

3. 3980 to 4080 (MV) 90'-10 sxs

4. 2500 to 2600 (PC) 100'-10 sxs

5. 2100 to 2350 (Ojo Alamo) 280'-24 sxs

5A. If csg cut off above Ojo Alamo, will set 50' plug in top of 4 1/2" casing stub.

6. 190 to 240 (Btm of Surf Csg) 50'-27 sxs

7. 0 to 30' in top of 10 3/4" surface casing - 16 sxs

Install marker and clean location

Verbal OK from Ed Schmitz on 9-3-74.

18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed by
MORRIS B. JONES

TITLE

Engineer

DATE

9-4-74

(This space for Federal or State office use)


APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.