

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 411	
2. NAME OF OPERATOR Union Oil Company of California		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
3. ADDRESS OF OPERATOR P. O. Box 2620 - Casper, Wyoming 82601		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL & 1650' FWL (NE NW)		8. FARM OR LEASE NAME Jicarilla 411	
14. PERMIT NO.		9. WELL NO. 1-6973	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7338' GR		10. FIELD AND POOL, OR WILDCAT Undesignated	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T.22N., R.3W.	
		12. COUNTY OR PARISH Sandoval	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6910' T.D. Completed as a producer on 1-26-71.

Plugged and abandoned subject well as follows:

Moved in and rigged up well service unit. P.O.O.H. with rods and tubing. Laid down seating nipple. Perforated nipple and Baker tubing anchor catcher. Ran 2-7/8" tubing open-ended to 6760'.

Plug #1, 21 sacks cement at 6910-6750'
Plug #2, 13 sacks cement at 4150-4050'
Plug #3, 39 sacks cement at 2450-2150'
Plug #4, 4 sacks cement at 20' to surface.

Cut off 8-5/8" casing and welded to 5-1/2" casing. Cemented and welded 4-1/2" D.P. Marker in top of 5-1/2" casing.

Well plugged and abandoned 5-31-73.

Above procedure approved verbally by Mr. Jerry Long, District Engineer, U.S.G.S., Durango, Colorado, on 5-16-73.

18. I hereby certify that the foregoing is true and correct

SIGNED

R. C. Ladd, Jr.

R. C. Ladd, Jr.

TITLE

District Drilling Supt.

DATE

6-2-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 7 1973

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.