

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Headset Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

USA-NM 58871

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Quinella

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undes Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 31, T23N, R6W

12. COUNTY OR PARISH 13. STATE

Sandoval

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Parko, INC

3. ADDRESS OF OPERATOR
903 W. Apache, Farmington, NM, 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
990 (FNL) 990' FWL
Re enter & complete in Gallup

14. PERMIT NO.

15. ELEVATIONS (Show whether of SLR or etc.)
G. L. 7293' KB 7106'

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLAN

(Other) Reenter abandon old well.

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Initiate 11-13-84 the drilling of the cement plugs to 4 1/2" casing stub at 1539', run Bowen Casing patch over stub after cleaning casing stub and milling off 5' of stub casing. To rerig up with work over rig run 3 1/2" bit on 2 3/8" tubing and drill out plugs to 5800'. Pressure test casing to 3000 psi. Test under packer if necessary to isolate old perforations. Perforate lower Gallup at depths on previous reports. Still doing geological evaluation of lower and upper Gallup.

See daily drilling and activity report.

RECEIVED

NOV 28 1984

RECEIVED

DEC 15 1984

DRILL

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

18. I hereby certify that the foregoing is true and correct.

SIGNED

Lloyd C. Parker

TITLE President

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DATE

12/10/84

ACCEPTED FOR RECORD

DATE

FARMINGTON RESOURCE AREA

sm

*See Instructions on Reverse Side