

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYCOPY REQUIRED
SUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved
Budget Bureau No. 42-R142
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2310' FSL 790' FEL Sec. 31 T23N R7W

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, CR, etc.)

GR 6891

NM-6681

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal C

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Alamito Gallup

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

31 T23N R7W

12. COUNTY OR PARISH

Sandoval

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and pertinent to this work.)

2/21/84: Believe well has casing failure. Intend to set RBP above Gallup perfs (4800-5158) and then use a packer to find the hole in the casing. Intend to repair said hole with cement, let cement set for at least 72 hours, then drill out cement, remove RBP, swab well and place back in production.

The above work was verbally approved by Ken Townsend with the Bureau of Land Management on this date.

RECEIVED

FEB 28 1984

OIL CON. DIV.
DIST. 3

APPROVED

FEB 24 1984

M. MILLENBACH
AREA MANAGER

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. Bigh

TITLE

President

DATE

2/21/84

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MOCC

*See Instructions on Reverse Side