

Pool Company oil/gas production services

Geneiny -

Please drop me a noto ex your convenience to advise an acceptable plugging procedure on this well. al may have already discussed may have already discussed it with Jarry Bedford, I will call the U.S.G.S. after learing from you.

Regards, Genden Brongentral Texas

Big Lake	Source	San Angelo	Sweetwater
884-2536	387-2884	653-2491	235-3250
563-2630	387-2664	563-2403	235-2846
Big Spring 263-8992 YJ7-4928	Rocksprings 387-2884 387-2664	Eldorado 853-2453 Abilene 692-6937	Winters 754-5217 673-9094

FIRST STATE BANK BUILDING ABILENE, TEXAS 79604

POST OFFICE BOX 23

July 7, 1975

4/2 2435-w 256 PC 2770
6960-7100 | Mu 4663

FL 4903

5000 - 51100 (where Get 5849)

4270-24370 for NW

44, 2710 - 2710 Conservation Commission

1000 Rio Brazos Road

5-2400-2500 2000 TD 7433

Attention: Mr. E. C. Arnold 6 200 1111 111 Attention: Mr. E. C. Arnold D. 3,0 - Miles (v. -

> Re: North American Exploration Corp. M-31-23-2 #1 Crosswise

Sandoval County, New Mexico

Gentlemen:

We have received a copy of the Field Inspection dated 7 May 75 concerning the captioned well, noting fence repairs were required, which was addressed to Tesoro Petroleum Corp.

This well has been removed from production status, and tubing and rods have been pulled. We plan to file a notice of intent to plug and abandon this month. The location will be properly restored after plugging.

Very truly yours,

NORTH AMERICAN EXPLORATION CORP.

GHG/jp

cc: L. L. Marquart - Tesoro

