

October 23, 1981

Petro-Lewis Corporation  
c/o Minerals Management  
928 Petroleum Building  
Denver, CO 80202

Re: Boling Federal #5      C-22-19N-3W

Gentlemen:

Annual packer tests on the above-referenced injection or SWD well indicate a packer or tubing leak.

In order to insure the protection of hydrocarbon bearing and fresh water zones, you are hereby directed to initiate remedial action within sixty days.

Yours truly,

Jeff A. Edmister  
Deputy Inspector

JAE:gc

cc: ~~Operator file~~ *well file*  
Petro-Lewis Corporation, Lindrith, NM  
Prentice Childs