13

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R1424 5. I EASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM 0554433

0.10100.0.12.00.11.2.								
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS			
43.1. 6		1 111						

is not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME WELL WELL X OTHER NAME OF OPERATOR 8. FARM OR LEASE NAME Chace Oil Company, Inc Rusty Federal 9. WELL NO. (OCATION OF WELL (Report location clearly and in accordance with any State requirements.*

At surface 313 Washington, S.E., Albuquerque, N.M. 87108 10. FIELD AND POOL, OR WILDCAT Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 800 FSL, 800 FEL Sec. 11, T22N, R7W
12. COUNTY OF PARISH 13. STATE 15. BLEVATIONS (Show whether DF. RT. GR. etc.) 14 FERVIT NO. 6990' GR Sandoval N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:					
	677.13		f			e			
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL				
PRACTURE TREAT	:	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING				
SHOOT OR ACTUIZE	1	ABANDON*	1 .	SHOOTING OR ACIDIZING	ABAN1:0NMENT*	i			
REPAIR WELL	: 1	CHANGE PLANS		(Other) Drilling Re	pert	x			
(Pher)				(NOTE: Report results of mult Completion or Recompletion Re	iple completion on Wel port and Log form.)	il			

- 17 DESCRIBE PROPOSES OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
- 3-23-74 Perforated 3507-11 with 8 shots - 2 shots per foot - started to pump in - Formation did not break down @ 2000 psia - shutdown for night.
- Started to swab @ 10 AM. Swab would not go through tight spot in 8 - 24 - 742-7/8" tubing @ 1800". Ordered undersized swab cup out of Houston.
- 8-25-74 Swab cups came in - started to swab at 3 PM found fluid at 750' and swabbed to 3300'. Shut down preparing to acidize with mud acid on Monday.

I hereby certify that the foregoing is true and correct				 14 A = 11 14			
SIGNED LILE	TITLE	Presid	ent	 	DATE 8-2	6-74	_
This space for Federal or State office use)				 = =.	, ar war salaw _a is la	÷ - ;	1 1 25
APPROVIE 79 CONSTITUTE OF APPROVAL, IF ANY:	TITLE			 _	DATE		
					AUG 28	1974	