

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
CONOCO INC. -

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Unit A

14. PERMIT NO.
790' FNL & FEL
30-043-20158

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.
Contract No. 45

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Ticarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
AXI Apache "P"

9. WELL NO.
4

10. FIELD AND POOL, OR WILDCAT
Ballard Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 19-23N-4W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) ☐	Plug and Abandon ☒	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU and set CIBP @ 2400'
- ② Spot 25 5x5 class "C" neat from 2400' to 1385'
- ③ Fill hole w/ weighted pkr fluid.
- ④ Perforate @ 271' w/ 4 JSPF, and establish circulation
- ⑤ Pump 100 5x5 Class "B" neat and circulate to surface, will not displace
- ⑥ Cut casing off a minimum of 3' below final restored ground ^{cm} level and erect abandonment marker
- ⑦ Clean location
- ⑧ Attached are proposed P4A wellbore and completion sketches

RECEIVED

JAN 09 1986

OIL CON. DIV
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE 1-2-86

(This space for Federal or State office use)

APPROVED
AS AMENDED

APPROVED BY

TITLE

DATE


CONDITIONS OF APPROVAL, IF ANY:

JAN 07 1986

John Miller
M. MILLENBACH
AREA MANAGER

*See Instructions on Reverse Side

F&A MAPAGE INCLUDES THE FOLLOWING:
 "AXI APACHE P NO. 4"
 "A-19-23N-4W"



BRIAN HORANOFF

12 DEC, 1985

PROCESSED F&A SKETCH
 AXI APACHE P NO. 4

AXI APACHE AREA
 NEW MEXICO

AXI APACHE "P" No. 4

LOCATION: 790' ENL + FEL OF SEC. 19, T-23N, R-4W

SPUDDED: 3 DECEMBER, 1974

COMPLETED: 5 MAY, 1975

ELEV: 6240' GL

ZERO: -0-

PERF BALLARD PICTURED CUTS 2431'-2460'.

FRAC 2431'-2460' w/5000 gal E-Z PAD,

14,000 gals. E-Z FLUID AND

34,000 # 20/40 SAND.


CAOF 593 MCFPD 1PF 588 MCFPD.

23 DECEMBER, 1977

WELL LOGGED OFF - SWABBED
TO PRODUCTION.

1 SEPTEMBER, 1985

SHUT-IN ... UNECONOMICAL TO
PRODUCE.



BAH

11-25-85