Form 9-331 (May 3963)	UNITED STATES DEPARTMENT OF THE INTE	SUBMIT IN TRIPLICAT (Other instructions on verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL WO. 14-08-0001-12395
(D. no)	SUNDRY NOTICES AND REPORTS see that form for the reaches and are to deeper a rich tree mapping without For Permit.	a to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	GAS 🗀	· · · · · · · · · · · · · · · · · · ·	7. UNIT AGREEMENT NAME
	WELL COTHER Gas Storage	Las Milpas Gas Storage	
	Union Gas Company	San Ysidro	
3. ADDRESS OF O	PERATOR		9. WELL NO.
4. LOCATION OF V See also space At surface	clity Union Tower, Dallas, Texas WELL (Report location clearly and in accordance with a p 17 below.)	Cluff #1-15 10. FIELD AND FOOL, OR WILDCAT Las Mildas	
	1908' FNL & 618' FEL Sec 19, F15N, P1E NETE	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA	
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	Soc 19 TISN RIE NMPM 12. COUNTY OR PARISH 18. STATE
	5930' Ungraded		Sandoval New Mexic
16.	Check Appropriate Box To Indicate		r Other Data
	NOTICE OF INTENTION TO:	SUBA	SEQUENT REPORT OF:
TEST WATER	SHUT-OFF UP TO OR ALTER CASTS:	WATER SHUT-OFF	REPAIRING WELL
FRACTI RE TA	NOT TO SELECT OF THE SELECT OF	FRACT: F TREATMENT	ALTERING CASING
Shoot or ac REPAIR WELL (Other)	· - · · · · · · · · · · · · · · · · · ·	SHOOTING OR ACIDIZING (Other) Spudding (Note: Report_resi	ABANDONMENT* Ilts of multiple completion on Well mpletion Report and Log form.)
1. Spude	ded 12 1/4" surface hole at 5:45	p.in. 7/2/7 5	
signed £	that the foregoing is true and correct TITLE Sharrock of Federal or State office use)	Geologist	DATE _7/3/75

*See Instructions on Reverse Side



DATE _____