Distribution:	Orig+4 (BLM);	1-Crystal; 1-Accounting; 1-Well File	f
Form 3160-5	UNI	TED STATES	FORM APPROVED
(June 1990)	DEPARTME	NT OF THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF	LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			NM-87227
Do not use this f	6 If Indian Allower or Tribe Name		
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for see 100 100 100 100 100 100 100 100 100 1			
	- THE EIGHTORY O	H PEHMIT—" for such proposals   W E	
	SUBMIT	IN TRIPLICATE IN TOOL	7. If Unit or CA, Agreement Designation
1. Type of Well		DEC 1 4 1994	
Oil Gas Well Well	Other		8. Well Name and No.
2. Name of Operator	Federal 12 C No. 1H		
Merrion Oil & G	9. API Well No.		
3. Address and Telephone I			
P. O. Box 840, Farmington, New Mexico 87499 (505) 327-9801			40. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Eagle Mesa Entrada
160! 6	11. County or Parish, State		
460' fsl & 330' fwl (SWSW) Section 12, T19N, R4W			Sandoval New Mexico
TACH IV			
THE THATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACTION			N
Notice of Intent  Subsequent Report		Abandonment	Change of Plans
		Recompletion	New Construction
		Plugging Back	Non-Routine Fracturing
Final Abandonment Notice Casing Repair			Water Shut-Off
	disconnent Ponce	☐ Altering Casing ☐ Other Drilling Report	Conversion to Injection
		Lis Oliei	Dispose Water (Note: Report results of multiple completion on Well
13. Describe Proposed or Cor	npieted Operations (Clearly state a	l pertinent details, and give pertinent dates, including estimated date of starts	Completion or Recompletion Report and Log (orm.)
give subsurface local	tions and measured and true vertice	al depths for all markers and zones pertinent to this work.)*	- p - p repeated work in work at directionally drinted.
11/10/94 MIRU	Four Corners Rig No. 8	. Drld mouse and rat hole. NU BOPs and wellhead.	Press tested to 1000 msi
	Cs and DP, TIH.	- 1-10 mouse and rat note. The Bot's and wermead.	ress tested to 1000 psr.
11/11/94 Mill 7	" casing from 5150! VD	to 5020LVD. Circulate alarm. Disale	
Mill 7" casing from 5150' KB to 5232' KB. Circulate clean. Displace mud out of hole with fresh water. POH. RI with drill pipe open-ended. Mix and spot 50 sxs Class 'H' with 2% CaCl2, yield 1.05#/cuft from 5232' KB to 4995 Pull above cement, reverse clean. POH.			ole with fresh water. POH. RIH
			5#/cuft from 5232' KB to 4995' KB
run a	bove cement, reverse clea	an. POH.	
11/10/04 DTT 6	1 (11) 3 777 1		
11/12/94 PU 6-1/4" MT bit, 16 each drill collars, 3-1/2" drill pipe. RIH. Tag cement top. Establish circulation. Commence drlg.			
	***CONTINUED	OTHER SIDE***	•
٨			
ſ:	17		
14. I hereby certify that the f			
4110	oregoing is true and correct		
Signed	<u> </u>	Title Operations Manager	Date11/30/94
(This space for space)	r Statil HimbH use)	Chief Landa Lan	D. # 4 . 0 . 400.4
Approved by Robert Kent Title Chief, Lands and Mineral Resources Date DEC 1 3 1994			
	•		
<del>=</del>			
Title 18 U.S.C. Section 1001, or representations as to any m	makes it a crime for any person interesting its jurisdiction.	knowingly and willfully to make to any department or agency of the Unite	d States any false, fictitious or fraudulent statements

\*See Instruction on Reverse Side