Form 9–331 • Dec. 1973	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES  DEPARTMENT OF THE INTERIOR	5. LEASE 25 5 5 6 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME 및 열
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME & SUPE
1. oil gas W other	8. FARM OR LEASE NAME & SUSSE Bradshaw Federals & Susse 9. WELL NO. 2282 & Susse
2. NAME OF OPERATOR	्रा अंशित का प्रस् राज्या
Kirby Exploration Company  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME 기술
P.O. Box 1745, Houston, Texas 77001  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF
below.) AT SURFACE: 1190' FNL & 1450' FEL	Sec 27 - 22N - 6W 25 2 2 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Sandoval New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT  SHOOT OR ACIDIZE	trong brust property of selection of selecti
REPAIR WELL  PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zon change on Form 9-330.) - நேர்ந்த
MULTIPLE COMPLETE  CHANGE ZONES	Priorition of the control of the con
ABANDON* (other)	rego de local no local no local no local maibre maibre lab des local modifica loc
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	irectionally drilled loive subsurface locations and
The subject well has been thoroughly tested and prequest permission to plug as follows:  spot cement plug 2100'19 spot cement plug 1650-19 Perforate at 1095 (50' below Ojo Alamo) and pump 25 to be at 1,000' (55" above Ojo Alamo) Perforate at 150' and pump 25 sacks class "B" ceme at 102'. Spot 10 sacks plug at surface. Set mark	roven to be morned of the beautiful ball of the beautiful ball of the ball of
spot cement plug 1650-19 Perforate at 1095 (50' below Ojo Alamo) and pump 2 to be at 1.000' (55" above Ojo Alamo)	550 See See See See See See See See See Se
Perforate at 150' and pump 25 sacks class "B" ceme at 102'. Spot 10 sacks plug at surface. Set mark	ent to tie into surface piped ker. Same programment
Surface will be returned to condition required by	nithmedia not benyes was landasi salabasi salaba
Subsurface Safety Valve: Manu. and Type	<u> </u>
18. I hereby certify that the foregoing is true and correct  Agent.	5 of 1-4-78 of 1-4-78
SIGNED John Alexander TITLE Agent  (This space for Federal or State offi	DATE
APPROVED BYTITLE	DATE DONAL THE DONAL THE DATE OF THE DATE
CONDITIONS OF APPROVAL, IF ANY:	the state of the s
*See Instructions on Regards	JAN 11 1978
20 1. D. DETHOCH SHOW	JAN 11 1978 OIL DIST. U.S. Geological Survey

U. C. OSCLOCICIL SURVEY

U.S. Geological Survey Farmington, M.M.