

**RIJAN OIL COMPANY, INC.**

20 FIRST PLAZA, SUITE 402  
ALBUQUERQUE, NEW MEXICO 87102  
(505) 243-0665

March 14, 1977


Mr. Jerry W. Long, District Engineer  
U. S. Geological Survey  
P. O. Box 1809  
Durango, Colorado 81301

Re: Rijan Oil Company, Inc.  
No. 1 PLR, Inc. well  
NW SW Section 23, T19N, R3W  
Sandoval County, New Mexico

Dear Jerry:

In connection with our application for a permit to drill the above-referenced well, please be advised that we plan to have a 10" Schaffer Double Gate Hydraulic Blow-Out Preventer (tested to 3000 psi) on the well during all drilling operations.

Sincerely,



Val R. Reese

VRR:mb

CC: Mr. John Arwood  
Bureau of Land Management

