SHOOT OR ACIDIZE

REPAIR WELL

(Other)

## UNITED STATES SUBM OEPARTMENT OF THE INTERIOR VERSE

SUBMIT IN TRIPLICATE\*
(Other instructions on re-

SHOOTING OR ACIDIZING

(Other) \_\_

Form approved.
Budget Bureau No. 42-R1424

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

	DEPARTMENT OF THE INTERIOR verse side)  GEOLOGICAL SURVEY	5. LEASE DESIGNATION A NM 31053	ND SERIAL NO.
	SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
1.	OIL GAS WELL OTHER	7. UNIT AGREEMENT NAM	110
2.	NAME OF OPERATOR	8. FARM OR LEASE NAM	C
	Dome Petroleum Corporation	Dome Alamos	
	ADDRESS OF OPERATOR %Minerals Management Inc., Suite 105,	9. WELL NO.	
٠	501 Airport Drive, Farmington, New Mexico 87401	1	
4. •	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface	Wildcat 11. SEC., T., R., M., OR BI SEC. 6, T211	J.K. AND
	1980' FSL, 900' FWL, SEC. 6, T21N, R6W	NMPM	· / Ron
14.	PERMIT NO.   15. ELEVATIONS (Show whether DF, RI, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	6803'GL, 6815' KB	Sandoval	N.M.
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or C	ther Data	
	NOTICE OF INTENTION TO: SUBSEQU	ENT REPORT OF:	
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING W	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11-24-77 Plugged and abandoned well as follows:

ABANDON\*

CHANGE PLANS

#1	6500'-6350'	150'	55	sx
#2	5510'-5460'	150'	55	sx
#3	4180'-4030'	150'	55	sx
#4	1794'-1644'	150'	55	sx
#5	675'- 325'	350 <b>'</b>	125	sx
#6	250'- 150'	100'	38	sx
#7	30'- 0'	30 <b>'</b>	10	sx

Erected marker and moved off. Location will be cleaned and pit fenced until dry. The pit will then be closed and the location seeded as per BLM stipulations.

## CONFIDENTIAL

			V. co. 7.3
18. I hereby certify that the sorgoing is true and correct SIGNED	TITLE	Area Manager Minerals Management Ind	CDATE 11-29-77
(This space for Federal or State office use)			g se pa st
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE