

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name NA	
2. Name of Operator Helton Engineering & Geological Services, Inc.		8. Farm or Lease Name Diamond Trail Ranch	
3. Address of Operator 860 Anaconda Tower, 555-17th Street, Denver, Colorado 80202		9. Well No. Brent No. 3	
4. Location of Well UNIT LETTER G, 2200 FEET FROM THE East LINE AND 2550 FEET FROM THE North LINE, SECTION 19 TOWNSHIP 13N RANGE 6E NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 5668' GL		12. County Sandoval	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>


SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Was Plugged And Abandoned as Follows on 8/6/79:

- Cleaned out bottom plug to 1972 ft.
- Set 50 sack plug from 1972 - 1810 ft.
- Set 85 sack plug from 1100-830 ft.
- Set 30 sack plug from 220-120 ft.
- Set 5 sack plug on top of surface pipe.
- Set dry hole marker.
- Cleaned and leveled location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerome B. Weber

TITLE \_\_\_\_\_

DATE 8/30/79

APPROVED BY AK Jendrick

TITLE \_\_\_\_\_

DATE 8/30/79

CONDITIONS OF APPROVAL, IF ANY: