

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Budget Bureau No. 1004-0135  
Expires August 31, 19855. LEASE DESIGNATION AND SERIAL NO.  
NM-6682

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal B

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Alamito Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 27 T23N R7W

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
(See also space 17 below.)

At surface

790' FSL 990' FWL Sec. 27, T23N R7W

RECEIVED

APR 20 1984

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, or BL)

GR 6948

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

12. COUNTY OR PARISH

Sandoval

13. STATE

N.Mex.

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4/19/84: Determined well has casing failure. Intend to set RBP above Gallup perfs (5042-5285) and then use a packer to find the hole in the casing. We intend to try to isolate the last casing failure (3420-3450) on this well during the process of finding and fixing the current hole unless they are close together and it can't be done.

The above work was verbally approved by John Keller with the Bureau of Land Management on Monday, April 23, 1984.

RECEIVED

APR 24 1984

OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. Bigbee

TITLE President

DATE 4/19/84

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

\*See Instructions on Reverse Side

APPROVED

APR 1984

J. M. MULLINBACH  
AREA MANAGER