

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-R1624

5. LEASE DESIGNATION AND SERIAL NO.
NM-16586

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant Ave., Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1850' FSL and 990' FEL Sec. 33 T23N R7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, AT, CR, etc.)

6866' GR

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal I

9. WELL NO.

2

10. FIELD AND FORM. OF WILDCAT

Undesignated Gallup

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec 33 T23N R7W

12. COUNTY OR PARISH 13. STATE

Sandoval

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PLUG OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT ON:

REPAIRING WELL

ALTERING CASING

ABANDONMENT

XX

(NOTE: Report results of multiple completion on Well.
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-29-83 Set RBP at 4608

11-30-83 Determined well has holes in the casing between 3488-3736. Advised Larry Pixley with BLM that we intended to repair same with cement on 12-1-83 at 8:00 A.M.

12-01-83 Set packer at 3182. Repaired hole in casing with 500 sacks class H 2% CaCl, 5/10% CFR-2 cement. Final squeeze pressure 1810 pounds.

12-05-83 to 12-07-83, Drilled cement 3351-3748. Pressure tested at 100#'s and held. Removed BP.

12-08-83 Swabbed well. Placed well back in production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. Boyle

TITLE

President

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
DATE 12/08/83

DEC 14 1983
DATE

FARMINGTON RESOURCE AREA

BY *8-11*

NMOCC

*See Instructions on Reverse Side