

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-R-1124

5. LEASE DESIGNATION AND SERIALIZED NO.

NM-6682

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation. Use APPLICATION FOR PERMIT for such proposals.)

6. IF INDIAN, NAME OF TRIBE AND NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal B

9. WELL NO.

4

10. FIELD AND FORM. OR WILDCAT

Undesignated Gallup

11. SEC., T. R., M. OR S. AND SURVEY OR AREA

Sec. 34 T23N R7W

12. COUNTY OR PARISH

Sandoval

13. STATE

NM

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1850 FSL 880' FWL Sec. 34 T23N R7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, CR, etc.)

GR 6886

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT ON:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and pertinent to this work.)

May 9, 1988 Rigged up. Tubing landed with 5138' (strapped pipe). Went in with bridge plug and packer. Set bridge plug at 3720'. Set packer and tested tools. Put 1500 lbs on well and left shut in overnight.

May 10, 1988 Well holding 1050 lbs. Packer not working. Brought tools out of hole and replaced packer. Went in with packer. Set bridge plug at 4720'. Tested tools. Located bad pipe between 3892' and 3938'. Came out of hole with packer. Dropped 10 gallons of sand on bridge plug. Received verbal permission to cement from Errol Beacher of BLM at 4:30 p.m.

May 11, 1988 Set packer at 3592'. Put 500 lbs on backside and squeezed with 200 sacks Class H with 1% CaCl mixed at 16.4 lbs with a yield of 1.08 or 216 cubic feet (approximately 38 bbls slurry). Closed valve. Squeeze holding at 1000 pounds.

May 12, 1988 Unset packer. Came out of hole. Went in with bit and bit sub. Tagged cement at 3782'. Drilled to 3875'. Cement too soft.

May 13, 1988 Drilled to 3906'. Cement still too soft to drill.

May 16, 1988 Drilled good cement to 3928'. Drilled 6 feet of stringers. Pressure tested. Casing held. Came out of hole with bit. Went in with (Continued)

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE Vice President

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
MAY 20, 1988

NMOCC

MAY 20 1988
FARMINGTON RESOURCE AREA
BY [Signature]

Operator: BCO, Inc.
135 Grant Ave.
Santa Fe, N.M. 87501

SUNDRY NOTICES AND REPORTS ON WELLS

Lease No: NM-6682
Federal B-4
Undesignated Gallup
Page Two

-
- May 16, 1988 retrieving head. Cleaned out sand on bridge plug, swabbed well dry, and retrieved bridge plug. Landed well at 5138' (strapped pipe). Swabbed well. Dropped piston.
- May 17, 1988 Swabbed well. Placed well in production.

RECEIVED
MAY 17 1988
MAY 17 1988
MAY 17 1988