								/	
Fo. m. 9-331 (May 1963)						16-	5. LEASE DESIGNATION AND SERIAL NO. NM-7246		
		TICES AND RE			rvoir.	- 6). IF INDIAN, ALBOTTEE	OR THIBE NA	ME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) 1. OIL UN GAS EN							7. UNIT AGREEMENT NAME		
WELL WELL X OTHER 2. NAME OF OPERATOR							8. FARM OR LEASE NAME		
Benson Mineral Group, Inc.							Federal 28-21-5		
3. ADDRESS OF OPERATOR							9. WELL NO.		
3200 Anaconda Tower, 555 17th St., Denver, CO 80202							1		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)							10. FIELD AND POOL, OR WILDCAT		
At surface						- 1	Wildcat		
1140' FSL & 1110' FEL, Section 28-T21N-R5W							11. SEC, T., R., M., OR BLK. AND SURVEY OR AREA Section 28-T21N-R5W		
14. PERMIT NO.		15. ELEVATIONS (Sh	ow whether DF, I	RT, GR, etc.)			12. COUNTY OR PARISH	13. STATE	
,,,		6922'					Sandoval	N.M.	
1.0			1 1: 1 NI	. (N) e B		. 04	nas Data	· · · · · · · · · · · · · · · · · · ·	
16.		Appropriate Box To	indicate 140	iture of Notice, is			T REPORT OF:		
NOTICE OF INTENTION TO:						sagea.	코		
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF						A	REPAIRING WELL		
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT							ALTERING CASING ABANDONMENT*		
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING CHANGE PLANS (Other) (Other)						لــــا	ABANDONMENT		
(Note: Report results							s of multiple completion on Well detion Report and Log form.)		
	SED OR COMPLETED Ok. If well is directork.)*	OPERATIONS (Clearly startionally drilled, give su	te all pertinent absurface location						any erti-
Please s	ee attache	ed list of d	lrilling	operation	s.				
spotting 1041-941	a 100' ce', and a	oup, Inc. ir ement plug i 10' cement p and a P&A m	n open olug at	hole secti surface.	on at	c ca	sing shoe f	rom	
						JAN	131979 CON. COM. DIST. 3		

JAN 15 1979

1/10/79

TITLE Production Manager

true and correct

. Ellison -


_PauY_C

(This space for Federal or State office use)

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY:

FEDERAL 28-21-5

- 1140 FSL and 1110 FEL, 28-21N-5W, Sandoval, NM.
- 9-1-78: WO evaluation of the Federal 4-20-5/TD 91'. Bit #1 1GS, 9 7/8". Time Distribution: Drl 1, Circ ¼, RC ¼, Cmt 1¼, LDDP ¼. Spud 14:00 8-31-78. 7" CSA 87' GR. Cmt x 50 sx Class "B" Neat, 3% CaCl. Plug down 17:00 8-31-78.
- 10-7-78: Circ/TD 1011'. Time Distribution: Drl $7\frac{1}{4}$, Circ 3, WO orders 4 3/4, reaming 1. Bit $\frac{1}{2}$ S3J $6\frac{1}{4}$ " made 911' in $7\frac{1}{4}$ hrs.
- 10-8-78: WOC/TD 1011'. Time Distribution: Run csg $2\frac{1}{2}$, cmt 3/4, LDDP 1, trip 1, circ 1. $4\frac{1}{2}$ " CSA 1011' GR. Cmt with 100 sx 50-50 poz, 6% gel, 50 sx Class "B" Neat. PD 13:15.
- 10-13-78: MI x RU pulling unit. Pick up 6 3 1/8" Drill collars x 3 7/8" bit.
- 10-14-78: TI, blowing down. Tag PBTD 1005'. Drl plug at 1006'. Drl formation 1010-13 x air. Did not blow any cuttings while drl. Made 15-20 gal slugs of water. Drl 1013-16, did not blow any cuttings while drl. Made blow of water. Drl 1016-1021. Did not blow any cuttings while drl. Circ x air for 30 min. Still did not blow cuttings.
- 10-15-78: TI x core barrel x 3 7/8" x 2 1/8" bit. Core 20' from 1021-1041 x foam. Strap out of hole x rec 20' sd.
- 10-17-78: SI WOO/Layed down drl collars x tbg.
- 10-26-78: SI WOO/SI 10 days, cpc 0, tpc 0.
- 10-31-78: SI/BHP 253 at 1000', FL 250' FS.



U. S. CANADONE IL SURVEY