	@w			6862 GL SpdSx. Pr Prod. Stim		\	w	Sx. T		@	T R
P	BO/D _MCF/D After	Hrs. SICP.	PSI	AfterDays GOR				lst_Del.		s	N 5
TOPS		NITD X		***************************************	+	TEST DATA				Ref.No.	
Kirtland		C-103		Plat X	Schd.	PC	Q	PW	- PD	-	F.61.140.
Fruitland		C-104		Electric Log	<b>_</b>	ļ	<del> </del>		<del> </del>		
Pictured Cliffs				C-122	<u> </u>		<u> </u>	<del> </del>	ļ		+
Cliff House		Ditr		Dfa	<b></b>		<u> </u>	ļ <u>-</u>	<b>-</b>	<del> </del>	
Menefee		Datr		Doc					<b>_</b>	<b>├</b> ──	<del>                                      </del>
Point Lookout							ļ <u> </u>	<u> </u>	<del> </del>	<del> </del>	<u> </u>
Mancos		1				<u> </u>		<u> </u>		-	<del> </del>
Gallup		-					ļ	<del> </del>	<del> </del>	<del> </del>	
Sanostee					<u></u>					<del> </del>	<del> </del>
Greenhorn		-				ļ		<del> </del>		ļ ——	<del></del>
Dakota	_					ļ	<u> </u>			<del> </del>	
Morrison		1		NOW 3 - 4-31		<u> </u>	<b>_</b>		<u> </u>	<del> </del>	
Entrada				231 60	.						
		1		211.50	' <u> </u>	<u> </u>					

Jicarilla 434 #1

B-5-22N-4W

Southland Royalty Company

## Federal Building 701 Camino del Rio Durango, Colorado 81301

April 18, 1979

Southland Royalty Company P. O. Box 570 Farmington, NM 87401

## Gentlemen:

This is to confirm my telephone call of April 10, 1979, advising you that the Conservation Division Chief has denied the approval of drilling of your proposed No. 1 Jicarilla Contract 434, located in the NE% sec. 5, T. 22 N., R. 4 N., and the No. 1 Jicarilla 435 located in the NW% sec. 10, T. 22 N., R. 4 W., Sandoval County, New Mexico, on Jicarilla Contract 434 and 435, respectively.

Memorandum of April 11, 1979, from the Acting Chief, Conservation Division of the Geological Survey to the Oil and Gas Supervisor, Albuquerque, New Mexico, instructs the District Engineer to return the applications to drill unapproved, unless there is reason to believe that one or both wells are necessary to protect the leases from drainage.

The memorandum further instructs that if it is felt that the drilling of the proposed wells should be permitted in order to protect the two leases against a present or potential drainage situation, the District Engineer should submit a written report through channels detailing the circumstances involved. The Division office would transmit that showing to the Department with their recommendations and request a decision as to whether the drilling of said well(s) may be approved.

Consequently, the APD's for the above wells are returned herewith unapproved.

Sincerely yours,

(Orig. Egd.) J. W. LONG

Jerry W. Long District Engineer APR & 0 1979
OIL CON. COM.
DIST. 3

Enclosures

cc: NMOCC / BIA, Dulce