

N

30-043-20392

10-3-78

F. Loc. 800/S; 1560/E Elev. 6993 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @  
Csg. Perf. Prod. Stim.T  
R  
A  
N  
S

IP BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. Ist Del. s

TOPS		NITD	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-103	Plat							
Fruitland		C-104	Electric Log							
Pictured Cliffs			C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout		150								
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										

P  
o  
o  
i

Cna Co. SA S 21 T 22N R 6W U 00per. Benson Mineral Grp Inclse. Navajo 21-22-6 No. 1

Navajo 21-22-6 #1

0-21-22N-6W

Benson Mineral Group, Inc.

Federal Building  
701 Camino del Rio  
Durango, Colorado 81301

February 14, 1979

Benson Mineral Group, Inc.  
3200 Anaconda Tower  
555 17th Street  
Denver, CO 80202

Gentlemen:

Reference is made to your letter dated February 8, 1979, which advises that you will not drill the following wells in Sandoval County, New Mexico:

<u>Well No.</u>	<u>Location</u>	<u>Lease No.</u>
<del>1</del> Navajo 21-22-6	SWSE 21-22N-6W	N00-C-14-20-5040
1 Navajo 34-22-6	SWNW 34-22N-6W	N00-C-14-20-5051

Applications for Permit to Drill have not been approved.

Drilling had not commenced on these wells. Any construction on access roads or well pads will have to be restored to the satisfaction of the Bureau of Indian Affairs.

Applications for Permit to Drill are rescinded this date and are returned herewith, unapproved. If at some later date you decide to drill these wells, it will be necessary to file new applications.

Sincerely yours,

Carl A. Barrick

Carl A. Barrick  
Acting District Engineer

cc: BIA, Crownpoint  
BIA, Window Rock  
NEIOCC, Aztec

