

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-11928

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WILDCAT	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Coleman Oil & Gas, Inc.	8. FARM OR LEASE NAME BOC
3. ADDRESS OF OPERATOR 6109 Del Campo Pl N.E. Albuquerque, New Mexico 87109	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1570'FSL, 810'FWL	10. FIELD AND POOL, OR WILDCAT WILDCAT
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T22N, R1W
15. ELEVATIONS (Show whether DE, RT, GR, etc.) 7677 Gr.	12. COUNTY OR PARISH Sandoval
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 2395, Prep to P & A.

Lost drag bit in casing shoe.

Propose to P & A as per following in accordance with verbal instructions issued by Richard Bell, 8:15 AM on 6-15-1981.

1. Set 500' Class B cement plug 1880-2380.
2. Back off 1 joint 4½ casing or perf sqz holes at 200' so as to place cement plug from 50' above to 50' below surface casing, shoe at 137'.
3. Install dry hole marker.



18. I hereby certify that the _____ is true and correct

SIGNED Flaude L. Kennedy TITLE Agent DATE 6-24-1980

(This space for Federal or State official use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

DATE _____
APPROVED
JUL 01 1981
Dean Elliott
DISTRICT ENGINEER