

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
Lewis Energy Corporation

3. ADDRESS OF OPERATOR
908 E. Navajo, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FSL 990' FWL
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒



5. LEASE
N00-14-20-5829

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo

7. UNIT AGREEMENT NAME
None

8. FARM OR LEASE NAME
Lopez

9. WELL NO.
#1

10. FIELD OR WILDCAT NAME
Wildcat Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 8 T20N R4W NMPM

12. COUNTY OR PARISH
Sandoval

13. STATE
New Mexico

14. API NO.
None

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well produced 100% water during swab test. For this reason we have plugged and abandoned this well. We tripped in hole w/2" tubing to 4080'. Spotted a 50 sx plug @ 4080', pulled 25 jts. tubing and pressured up for squeeze. Left top of cement inside 7" @ 3980'. Perf. 2 holes @ 2144, spotted 35 sx 2144'-2044' inside and out. Perf 2 holes @ 1577'. Spotted 35 sx 1577'-1477' inside and out. Perf. 2 holes 1220'. Spotted 35 sx 1220' to 1120' inside and out. Perf 2 holes 835'. Spotted 35 sx 835' to 735' inside and out. Perf 2 holes @ 480'. Spot 35 sx 480'-285' inside and out. Perf 2 holes @ 276'. Spotted 35 sx 276'-176' inside and out. Set 50' surface plug. Installed P&A marker. 9.2# Drilling mud was used between plugs. Work was done 10/21/82 to 10/25/82. All pits have been filled, trash removed, location graded, anchors removed. Reseeding to be done on or about 5/1/83 as per BIA instruction.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Zachary C. Lewis TITLE Operations Mgr. DATE 10/27/82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON COPY

*See Instructions on Reverse Side

