UNITED STATES DEPARTMENT OF THE INTERIOR

1	5. LEASE	DESIGNATION	AND	SERIAL	NC
---	----------	-------------	-----	--------	----

• •	BUREAU OF LAND MANAGEMENT					
SUNDRY NOTICES AND REPORTS ON WELLS					6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
				·	7. UNIT AGREEMENT NAI	
" bin Africa Alekane	., 13.11.				7. UNIT AGREEMENT NA	MC.
OILWELL [xx] GAS WELL []	ELL [xx] GAS WELL [] OTHER					
2. NAME OF OPERATOR	The Gary-Williams Company WTO 14 DE Ples. Chice,			8, FARM OR LEASE NAME Johnson		
		0. 0. 1005	<u> </u>		9. WELL NUMBER	
3. ADDRESS OF OPERATOR	1775 Sherman St., Ste 1925 Denver, CO 80202 (303) 831-4673			4-14		
	Denver, CO 80	3202 (303) 0	01-4010		10. FIELD AND POOL, OF	RWILDCAT
4. LOCATION OF WELL			Rio Puerco - Mancos			
AT SURFACE 860' fsl, 165	0' fwl			11. SEC., T., R., OR BLK. AND SURVEY		
			: "		Sec. 4 - T20N - R2	
		15 ELEVATIONS			12. COUNTY OR PARISH	13. STATE
14. PERMIT NO.		6868 K	R		Sandoval	N. M.
	Chack Appl		ate Nature of Notice,	Report, or	Other Data	
16.	• •	Topriate Box 10 maio	j.	SUBSEQUENT RE		
NOTICE OF INTE	PULL OR ALTER C	ASING ()	WATER SHUT-OFF	[]	REPAIR WELL []	
TEST WATER SHUT-OFF []	MULTIPLE COMPL		FRACTURE TREATM		ALTERING CASING [1
FRACTURE TREAT []	ABANDON	[xx]	SHOOTING OR AC	DIZING []	ABANDONMENT []	
SHOOT OR ACIDIZE []	CHANGE PLANS	[]	(OTHER)			
REPAIR WELL []	CIANGET BING		_	0		
(OTHER) [] 17. DESCRIBE PROPOSED OR COMP	PLETED OPERATIONS		.,	ş		¥ & 4
REVISED 4/20/93. Verbal ap		v Robert Kent, BLM Petr	oleum Engineer	1		\$
We submit the revised prop					~ APR 2 6 18	393
			11. 12	ail.	OH CON	T2926
A free point log run 4/1	7/93 indicates th	- ne 5 1/2" casing is stuck (ell diagram for casing det @ 750', necessitating the	change in p	lugging procedure.	heriore.
1. Set a 275 ft. cement plug	from 3675' to 34	100' accross the base of	the 5 1/2" casing.		\	s.,
2. Perforate the 5 1/2" casis						
3 Set a cement retainer at	2900'.					
4. Stab into the retainer an	d inject the reser	ve pit fluids from the Org	uidea 4-1H well. The Orq	uidea well is	located on the same	Federal lea
5. Pull out of the retainer a	nd check for flow	back. Set a 50 ft. cemen	t plug on top of the retain	er.		
6. Perforate the 5 1/2" cast						
7. Circulate cement between) en the 5 1/2" and :	8 5/8" csg. Leave a ceme	nt plug inside the 5 1/2" o	asing from 7	750' to surface.	
8. Surface restoration will	not take place im	mediately because the J	ohnson 4-14 production f	acilities are	now being used for p	oroduction fr
the Orguidea 4-1H well.						
H						
18. I hereby centry the ree foregoing	e true and correct				1.0	
SIGNED	41).	_ TITLE Attorney-	in - fact	DATE 4/2	1/ 4.3	
(This space for Federal or State of	ffice use)	ActingAREA MA	NAGER	Λn	D 0 0 1000	
APPROVED BY SHIRLE			O RESOURCE AREA	DATEAP	R 23 1993	
CONDITIONS OF APPROVAL, IF AN	Υ:					

NMOCD