

3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
West Largo Corp.

3. Address and Telephone No.
6638 W. Ottawa Ave., Suite 100, Littleton, CO 80123 (303) 932-1851

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
850' FSL, 1850' FEL, (SWSE) Sec 18, T21N-R5W, NMPM

5. Lease Designation and Serial No.
NMNM 35480

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Natani #25

9. API Well No.
30-043-20608

10. Field and Pool, or Exploratory Area
Rusty Chacra

11. County or Parish, State
Sandoval, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

RECEIVED
JUL 1 9 1995
OIL CON. DIV.
DIST. 3

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance with Sundry Notice dated 6/23/95, if this well proves to be incapable of producing hydrocarbons in paying quantities, West Largo Corp. hereby proposes to plug and abandon (P&A) this well per the procedure described below: (see attached wellbore schematic)

- 1) MIRU Completion rig.
- 2) Kill well w/ wtr.
- 3) GIH w/ tbg to middle of Rusty Chacra perfs @ 1600'. Set 200' cmt plug across perfs from 1700' to 1500'. POH w/ tbg.
- 4) Set plug @ surface w/ 10 sx in 4-1/2" csg.
- 5) Instl P&A marker, remove surface equipment, restore location.

RECEIVED
BLM
55 JUN 29 PM 1:26
070 PALMINGTON, NM

14. I hereby certify that the foregoing is true and correct

Signed J.P. Garrett

Title Designated Agent

Date 6/27/95

(This space for Federal or State office use)

Approved by [Signature]

Conditions of approval, if any:

[Signature] Title Chief, Lands and Mineral Resources

Date JUL 1 8 1995

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

OPERATOR